UNCLASSIFIED

AD NUMBER

AD376819

CLASSIFICATION CHANGES

TO: unclassified

FROM: confidential

LIMITATION CHANGES

TO:

Approved for public release, distribution unlimited

FROM:

Distribution: USGO: others to Director, Defense Atomic Support Agency, Washington, D. C. 20301.

AUTHORITY

DSWA ltr., 10 Apr 97; DSWA ltr., 10 Apr 97

THIS PAGE IS UNCLASSIFIED

376819 CONFIDENTIAL

DREMNSE ATOMIC SUPPORT ASSAUR

MEC RESEARCH AND DEVELOPMENT REPORT

Facsimile

Report

ATOMIC ENERGY COMMISSION UNITED STATES

Reproduced by

Division of Technical Information

Oak Ridge, Tennessee 37831 P.O. Box 62

PROM ANTOMATIC


CONFIDENTIA

Inc! 1 of

This material contains information affecting the national defense of the United States within the meaning of the espionage laws, Title 18, U.S.C., Secs. 793 and 794, the transmission or revelation of which in any manner to an unauthorized person is prohibited by law.

IN ADDITION TO SECURITY REQUIREMENTS WHICH APPLY TO THIS DOCUMENT AND MUST BE MET, EACH TRANSMITTAL OUTSIDE THE AGENCIES OF THE U.S. GOVERNMENT MUST HAVE PRIOR APPROVAL OF THE DIRECTOR, DEFENSE ATOMIC SUPPORT AGENCY, WASHINGTON, D.C. 20301.

CONFIDENTIAL




(14) XKD-17

CONFIDENTIAL

(7) BUREAU OF SHIPS GROUP

TECHNICAL INSPECTION REPORT

Downgraded at 12 year intervals Not Automatically Declassified GROUP 3



CONFIDENTIAL Security Information

USS ARKANSAS (BB33), /

Lanination !


Page 1 of 177 Pages (Lung of 2)

CONFIDENTIAL

(L) BA-CR-198-188-31. View from dead ahead before Test A.

CONFIDENTIA

Page 2 of 177 Pages



AA-CR-227-81-43. View from dead shead after Test A.

REMEMBERS 1914 CONFIDENTIAL

ATOMIC BURGE ACT 1948 Security Information

Page 3 of 177 Pages

BA-CR-198-186-32. View from port bow before Test A. CONFIDENTI,

of 177 Fages

CONFIDENTIAL Sounty Properties



AA-CR-227-91-44. View from port bow after Test A.



Page 5 of 177 Pages


USS ARKANSAS (BB33)



BA-CR-150-166-33. View from port beam before Test A.



USS ARKANDAS (BB33) Page 6 of 177 Pages




AA-CR-227-91-45. View from port beam after Test A.



Page 7 of 177 Pages

USS ARKANSAS (BB33)



USS ARKAINSAS (BB33)



BA-CR-196-166-34. View from port quarter before Test A.





AA-CR-227-91-38, Vlew from port quarter after Test A.


USS ARKANSAS (BB33) Page 9 of 177 Pages SECRET



BA.CR-196-166-29, View from off stern before Test A.

Page 10 of 177 Pages

SECRET



AA-CR-227-91-39. View from dead astern after Test A.

Page 11 of 177 Pages


USS ARKANSAS (BB33)

Page 12 of 177 Pages

BA-CR-196-166-28. View from starboard quarter before Test A.

USS ARKANSAS (BB33)

SECRET



AA-CR-227-91-40. View from starboard quarter Meer Test A.


Page 13 of 177 Pages

SECRET

USS ARKANSAS (BB33)

USS ARKANSAS (BB33) Page 14 of 177 Pages

SECRET



BA-CR-136-166-27. View from starboard beam before Test A.



AA-CR-227-91-41. View from starboard beam after Test A.

Page 15 of 177 Pages SECRET

USS ARKANSAS (BB33) 9226

SECRET

Page 16 of 177 Pages

BA-CR-196-166-30. View from starboard bow before Test A.



AA-CR-227-91-42. View from starboard bow after Test A.


USS ARKANSAS (BB33) Page 17 of 177 Pages

• USS ARKANSAS (BB33)

AA-CR-62-1861-1. Port side, bow to frame 102.

Page 18 of 177 Pages

SECRET



AA-CR-82-1774-11. Close-up of port side, frames 30 to 100.

OSS ARKANSAS (BB33)
Page 19 of 177 Pages

SECRET

Page 20 of 177 Pages

AA-CR-62-1861-2. Port side, frame 38 to stern.



AA-CR-92-1774-12. Port side, frames 92 to 132.


Page 21 of 177 Pages

USS ARKANSAS (BB33)

SECRET

AA-CR-92-1774-6. Starboard quarter.

USS ARKANSAS (BB33) Page 22 of 177 Pages



AA-CR-92-1774-7. Starboard side, frames 30 to 110.

SECRET

Page 23 of 177 Pages

USS ARKANSAS (BB33)



AA-CR-92-1774-8. Starboard side, frame 10 to 60.

Page 24 of 177 Pages



AA-CR-68-2091-3. View looking aft at forward superstructure showing S.K. radar mast and yardarms damaged.

Page 25 of 177 Pages

USS ARKANSAS (BB33)

AA-CR-68-2097-3. General view looking forward from mainmast showing damage to foremast structure.

SECRET

Page 26 of 177 Pages

USS ARKANSAS (BB33)

6526



AA-CR-68-2094-1. Forward yardarms, S.K. radar pole and platform on foremast.

Page 27 of 177 Pages

UBS ARKANSAS (BB33)



AA-CR-68-2094-2. Radar platform on forward tripod showing deformation of starboard wing and after section.

SECRET

Page 28 of 177 Pages




AA-CR-175-2135-6. Condition of underside of after part of radar platform on foremast. Note that horizontal cable runs show no signs of neat damage.

Page 29 of 177 Pages

USS ARKANSAS (BB33)

9526




AA-CR-68-2094-4. Looking to starboard at top of main battery director showing r at window pilasters.

SECRET

Fage 30 of 177 Pages

USS ARKANSAS (BB33)



AA-CR-68-2091-1. Looking aft from frame 35, port, main deck at damage to foremast.

Fage 31 of 177 Pages

USS ARKANSAS (BB33)

Page 32 of 177 Pages

SECRET

AA-CR-175-2135-4. Condition of pole mast supporting radar platform on foremast. Note beads of insulation protruding through cable armor.

USS ARKANSAS (BE33)

9226




AA-CR-C8-5344-9. Lucking down on starboard side of top of fire starts station, frame 48 to 51. Instrument panel blown down by blast fraction, reche fluches in reck.

USS ARKANSAS (BB33) 9 2 5 6 STABLE LL TO BE SELECT



 $AA\mbox{-}CR\mbox{-}68\mbox{-}2094\mbox{-}5.$ Looking down on starboard side of fire control station.

USS ARKANSAS (BB33) Page 34 of 177 Pages SECRET



AA-CR-68-2095-1. Looking upward at bulwark on port side of the fire control station.

Page 35 of 177 Pages

USS ARKANSAS (BB33)

9576

AA-CR-68-2094-6. Looking cutboard at starboard wing of top of fire control station.

SECRET

Page 36 of 177 Pages



AA-CR-68-2095-9. Lo~king forward at after side of foremast showing rangefinder platform lifted by blast and louse distorted on navigation bridge level.

Page 37 of 177 Pages

USS ARKANSAS (BB33)

9526

AA-CR-68-2094-11. Port tripod leg of foremast at connection of range-finder platform supports.

SECRET

Page 38 of 177 Pages

USS ARKANSAS (BB33)




AA-CR-68-2094-10. Failure in port tripod leg of foremast at connection of rangefinder platform support.

Page 39 of 177 Pages

USS ARKANSAS (BB33)


9226



AA-CR-175-2135-3. Fracture of starboard foremast tripod leg in way of cantilever support for rangefinder platform, looking upward and outboard.

SECRET

USS ARKANSAS (BB33) Page 40 of 177 Pages



AA-CR-92-1782-12. Detail of fracture in starboard foremast tripod leg caused by lifting of rangefinder platform.

Page 41 of 177 Pages

USS ARKANSAS (BB33)



AA.-CP. 68-2094-8. Failures in starboard tripod leg of foremast, looking inboard.

SECRET

Page 42 of 177 Pages



AA-CR-92-1782-11. Detail of crack in starboard tripod leg which was initiated at welded connection.

Page 43 of 177 Pages

USS ARKANSAS (BB33)

AA-CR-68-2094-12. Fire control station, broken connection frame 52, starboard. Movement of cables in tubes due to structural damage.

SECRET

Page 44 of 177 Pages




AA-CR-68-2095-2. Looking to starboard at damage to forward bulkiead of shack on after end of navigation bridge.

Page 45 of 177 Pages

SECRET

USS ARKANSAS (BB33)

9256




MA-CR-68-2095-6. Looking to starboard at life jacket locker, bridge deck, showing remains of flag bag from overhead.

SECRET

Page 46 of 177 Pages

USS ARKANSAS (BB33)

9526




AA-CR-68-2095-5. Looking aft at life jacket locker, port side of bridge deck, frame 53. Stack in background.

Page 47 of 177 Pages

SECRET

USS ARKANSAS (BB33)

9256




AA-CR-68-2095-4. Forward side of ready service locker, bridge deck, frame 48, port.

SECRET

Page 48 of 177 Pages

USS ARKANSAS (BB33)

9256



AA-CR-68-2095-7. After side of ready service locker, bridge deck, frame 48, starboard.

USS ARKANSAS (BB33) Page 49 of 177 Pages

Page 50 of 177 Pages


SECRET

AA.CR.68-2095-3. Damage to back of ready service locker, bridge deck, frame 48, port, looking down between locker and bulkhead.



AA-CR-92-1775-7. Looking to port through transverse passageway, frames. 52 to 55, superstructure deck. Remains of burned U.S. Army equipment in foreground.

USS ARKANGAS (BB33) Page 51 of 177 Pages



AA-CR-68-2091-4. Looking forward and inboard from frame 59, starboard, superstructure deck. Showing damage to light metal structure and burned areas of wood deck.

SECRET

Page 52 of 177 Pages


USS APKANGAS (BB33)



AA-CR-68-2095-12. Hood over vent trunk, superstructure deck, frame 60, starboard.

Page 53 of 177 Pages

USS ARKANSAS (BB33)



AA-CR-68-2147-3. Overall view of starboard boom, looking forward and outboard from frame 70.

SECRET

USS ARKANSAS (BB33)
Page 54 of 177 Pages



AA-CR-58-2146-4. Crane boom, frame 62, starboard side, superstructure deck.

SECAET


Page 55 of 177 Pages

. Uns ARKANSAS (BB33)

Page 55 of 177 Pages

SECRET

AA-CR-80-1897-7. Damage to smokestack.



AA-CR-80-1897-6. Damage to smokestack.

Page 57 of 177 Pages

USS ARKANSAS (BB33)

r{

AA.CR-92-1775-10. Looking aft from foremast, showing stack cap, damaged stack and starboard crane.

SECRET

Page 58 of 177 Pages



A4-CR-68-2091-6. General view looking aft from bridge deck. Damaged stack is in foreground. Starboard searchlight missing from after searchlight platform.

Page 59 of 177 Pages

USS ARKANSAS (BB33)

.4A-CR-80-1397-8. Damage to smokestack, uptakes and uptakes weather bulkhead.

SECRET

USS ARKANSAS (BB33) Page 60 of 177 Pages



AA-CR-68-2095-11. After bulkhead of deck house frame 68, superstructure deck.

Page 61 of 177 Pages

USS ARKANSAS (BB33)


9526



AA-CR-68-2091-5. General view, looking aft from starboard side of bridge deck.


SECRET

Page 62 of 177 Pages



AA-CR-68-2090-4. Looking forward in starboard aircastle.


USS ARKANSAS (BB33) Page 63 of 177 Pages



AA-CR-68-2090-12. Looking forward in port air castle.

SECRET

USS ARKANSAS (BB33) Page 64 of 177 Pages



AA-CR-68-2090-5. Looking aft at frame 41, starboard, showing damaged gun port cevers.

, SECRET

Page 65 of 177 Pages

USS ARKANSAS (BB33)

AA-CR-175-2135-1. Looking forward at damage and scorching of paint near door at after end of port aircastle, main deck frame 61, port.

USS ARKANSAS (BB33)

Page 66 of 177 Pages



AA-CR-175-2134-9. Looking upward at blast damage to gun platform, superstructure deck, frame 66 to 73, starboard. This view is taken from the approximate angle of approach of the blast.

Page 67 of 177 Fages SECRET


U3S ARKANSAS (BB33)

AA-CR-68-2095-10. Damage to gun platform and bulwark, superstructure deck, frame 68 to 72, starboard. Note hatch cover from hatch to boat shop.

SECRET

Page 68 of 177 Pages

USS ARKANSAS (BB33)



AA-CR-38-2097-12. Looking forward at blast damage to gun platform, superstructure deck, frames 66 to 73, starboard.

Page 69 of 177 Pages

USS ARKANSAS (BB33)


9526

AA-CR-68-2030-3. Looking forward and inboard at deckhouse buikhead, main deck, frame 63 to 68, starboard.

SECRET

Page 70 of 177 Pages

USS ARKANSAS (BB33)



AA-CR-2097-11. Looking forward and inboard at dished deckhouse bulkhead main deck, frames 63 to 68, starboard.

Page 71 of 177 Pages

USS ARKANSAS (BB33)



AA-CR-92-1775-6. Looking forward and inboard at deck house bulkhead, frames 65 to 68, starboard.

SECRET

Page 72 of 177 Pages

USS ARKANSAS (BB33)



AA-CR-175-2134-11. Looking forward and inboard at dished deckhouse bulkhead main deck, frames 63 to 68, starboard.


Page 7" of 177 Pages

USS ARKANSAS (BB33)

AA-CR-92-1782-8. Close-up view of buikhead plating faiture adjacent to stiffener. Note stiffener rivets pulled through buikhead. See photo No. 2134-11.

SECRET

USS ARKANSAS (BB33) Page 74 of 177 Pages



AA-CR-92-1782-9. Detzil of torn bulkhead plating, frame 64, starboard side, main deck. See photo No. 2090-3.

Page 75 of 177 Pages

USS ARKANSAS (BB33)


9226

AA-CR-82-1782-10. Detail of plating and door frame failure at frame 63, starboard side, main deck.

SECRET

Page 76 of 177 Pages


USS ARKANSAS (BB33)



AA-CR-68-2091-10. Damage to quick acting door in bulkhead 73, main deck starboard side, and ready service box adjacent to the door.

Page 77 of 177 Pages

USS ARKANSAS (BB33) 9256




AA-CR-68-2090-11. Looking forward and inboard at deckhouse bulkhead, frames 62 to 68. Port main deck.

SECRET

Page 78 of 177 Pages

USS ARKANGAS (BB33)



AA-22-175-2134-12. Looking forward and inboard at damage to outboard blike at of deckiduse, main deck, frames 63 to 67, port.

136010

USS ARKANSAS (BB33) Fage 79 of 177 Fages

* 256

USS ARKANSAS (BBSS)

Page 80 of 177 Pages



AA-CR-80-1895-7. Forward area of after tripod, looking to port, showing main mast hanging top down.


Page 81 of 177 Pages

USS ARKANSAS (BB32)

USS ARKANSAS (BB33)

AA-CR-80-1895-6. General view of main deck and rortion of main mast structure. Note that top of mast is in debris on deck.

Page 82 of 177 Pages



AA-CR-80-1895-9. Detail of top of mainmast.

Page 83 of 177 Fages

USS ARKANSAS (BB33)

USS ARKANSAS (BB33)

AA-CR-80-1895-8. Detail of lower end of mainmast and yardarm.

Page 84 of 177 Pages




AA-CR-80-1895-10. Detail of base plate and yardarm brackets - nainnast.

USS ARKANSAS (BB33) Page 85 of 177 Pages

USS ARKANSAS (BE33)

AA-CR-80-1895-11. Remains of doubler at base of main topmast. Cables parted due to failure of mast.

Page 86 of 177 Pages



AA-CR-68-2091-7. View of mainmast showing damage on various levels and entire structure slightly canted forward and to port.

Fage 87 of 177 Pages

USS ARKANSAS (BB33)

AA-CR-68-2097-7. Failure of connection of after starboard leg of mainmast to main deck.

SECRET

USS ARKANSAS (BB33) Page 88 of 177 Pages



AA-CR-68-2145-5. 2nd deck, base of starboard aft leg, frame 103.

Page 89 of 177 Pages


USS ARKANSAS (BB33)



AA-CR-68-2146-6. Starboard aft leg, fram 103, underside main deck.

SECRET

USS ARKANSAE (BB33) Page 90 of 177 Pages



AA-CR-68-2146-7. Starboard aft leg, frame 103, underside of main deck, showing lifting of plate from longitudinals and beams.

Page 91 of 177 Pages


USS ARKANSAS (BB33)

AA-CR-68-2111-10. Port aft leg above wrapper plate - looking to starboard.

SECRET

Page 92 of 177 Pages


USS ARKANSAS (BB33)



AA-CR-175-2134-7. Port after leg of after tripod, looking to starboard, showing wrinkle at top of wrapper plate, see also 2111-10.

Page 93 of 177 Pages

USS ARKANSAS (BB33)




AA-CR-68-2111-9. Port aft leg-mainmast showing wrinkle between leg and wrapper plate.

SECRET

Page 94.of 177 Pages

USS ARKANSAS (BB33)



AA-CR-68-2089-9. Looking aft at wrinkle in forward leg of mainmast.

Page 95 of 177 Pages

USS ARKANSAS (BB33)


AA-CR-68-2111-7. Foreleg-mainmast tripod - looking at port side, wrinkle in leg.

SECRET

Page 96 of 177 Pages

USS ARKANSAS (BB33)

.




AA-CR-68-2111-8. Foreleg - mainmast tripod looking at wrinkle from starboard side.

Page 97 of 177 Pages

USS ARKANSAS (BB33)

9256



AA-CR-175-2134-8. Forward leg of after tripod showing wrinkling at top of wrapper plate, and opening of seam on port side.

SECRET

Page 98 of 177 Pages

USS ARKANSAS (BB33)



AA-CR-68-2146-10. Center leg, after tripod, frame 99, looking aft at underside of main deck.

Page 99 of 177 Pages

USS ARKANSAS (BE333)




AA-CR-66-2146-9. Center leg, after tripod, frame 99, looking aft at underside of second deck.

SECRET

Page 100 of 177 Pages

USS ARKANSAS (BB33)



AA-CR 38-2089-7. Looking forward from frames 103, port main deck. Showing damage to bulkhead and door of 20MM clipping room and bent stanchion supporting 20MM gun platform.

USS ARKANSAS (BB33) Page 101 of 177 Pages

AA-CR-68-2089-10. Looking inboard and aft at mainmast structure, note structure pulled upward at 01 level, starboard, after corner and forward stanchion buckled.

SECRET

USS ARKANSAS (BB33) Page 102 of 177 Pages



AA-CR-68-2111-11. Mainmast structure starboard side - looking forward and up at opening of structure at 01 level.


USS ARKANSAS (BB33) Page 103 of 177 Pages

Page 104 of 177 Pages.

SECRET

AA-CR-92-1783-4. Centerline of aft superstructure at frame 102, showing opening at 01 level. Note tear between 01 level deck and after bulkhead.

USS ARKANSAS (BB?3)



AA-CR-68-2146-3. Aft starboard leg, wrinkle in deck at 31 level.

Page 105 of 177 Pages

USS ARKANSAS (BB33)




AA-CR-66-2097-5. Mainmast structure 01 level, starboard. Dished door.

SECRET

USS Fage 106 of 177 Pages

USS ARKANSAS (BB33)



AA-CR-68-2089-8. Looking inboard from frame 98, port, towards bent stanchion supporting 20MM gun platform and at wrinkle in forward leg of mainmast.

Page 107 of 177 ∑ages

USS ARKANSAS (BB33)

AA-CR-68-2146-2. O2 level, showing crack around starboard aft leg of mainmast.

SECRET

Page 108 of 177 Pages

USS ARKANSAS (BB33)



AA-CR-68-2097-4. Mainmast, 03 level, starboard, broken pipe support for blinker searchlight.

USS ARKANSAS (BB33) Page 109 of 177 Pages

AA-CR-68-2097-1. Mainmast, 04 level, starboard, damage to bulwark and venturi.


SECRET

USS ARKANSAS (BB33) Page 110 of 177 Pages



AA-CR-68-2097-2. Mainmast, 04 level, port scorched paint and damage to equipment.

SECRET (BB33)
Page 111 of 177 Pages ***




AA-CR-92-1775-3. Looking aft at damaged 36 inch searchlight displaced from mainmast. Frame 82, port, main deck.

SECRET

USS 1 Page 112 of 177 Pages

USS ARKANSAS (BB33)



AB-CR-234-1991-1. Turret 4, right trunnion of right gun. Fracture in trunnion block at forward end of trunnion cup.

Page 113 of 177 Pages

USS ARKANSAS (BB33)

SECRET
Page 114 of 177 Pages

AB-CR-234-1991-2. Turret 4, right trumion of right gun. Crack in trumion block at after end of trumion cap.

USS ARKANSAS (BB33)




AB-CR-234-1991-4. Turret 4, right trumion of right gun. Displacement of trumion.

Page 115 of 177 Pages

USS ARKANSAS (BB33)


?/



AA-CR-80-1897-9. Looking aft at rangefinder displaced from atsp turret 2. Main deck starboard, frame 35.


SECRET

USS ARKANSAS (BBSC) Page 116 of 177 Pages



AA-CR-92-1775-9. Displaced rangefinder atop turret 5.

USS ARKANSAS (BB33)
Page 117 of 177 Pages




AA-CR-68-2091-2. Looking forward on forecastle from frame 28, port.

SECRET

Page 118 of 177 Pages

USS ARKANSAS (BB33)



AA-CR-68-2090-1. Looking forward along main deck from frame 90, starboard.

USS ARKANSAS (BB33) Page 119 of 177 Pages

9226

AA-CR-88-2090-2. Looking aft and inboard at starboard sides of turrets 3 and 4. Main deck is slightly dished in this area.

SECRET

Page 120 of 177 Pages


USS ARKANSAS (BBSS)



AA-CR-69-2089-2. Looking forward and to port showing damaged area of main deck aft of turret 6.

Page 121 of 177 Pages

USS ARKAIWSAS (BB33)



AA-CR-68-2069-1. Looking forward towards Turret 6 showing damaged area of main deck.

SECRET

Page 122 of 177 Pages

USS ARKANSAS (BB33)



AA-CR-68-2089-3. Looking forward and to starboard showing damaged area of main deck aft of Turret 6.

Page 123 of 177 Pages

USS ARKANSAS (BB33)

Page 124 of 177 Pages

SECRET

USS ARKANSAS (BB33)

AA-CR-92-1775-1. Looking forward and to starboard at dished area of main deck aft of Turret 6.



AA-CR-178-1134-3. Major deck depression in main deck aft of Turret of at about frame 125.

Page 125 of 177 Pages


THELL

USS ARKANSAS (BB33)

AA-CR-68-2089-5. Looking to starboard at frame 123, showing damaged area of main deck.

SECRET

USS ARKANSAS (BB33) Page 126 of 177 Pages




AA-CR-68-2089-4. Looking to port at frame 123, main deck, showing damaged area of main deck.

USS ARKANSAS (BB33) Page 127 of 177 Pages

AA-CR-68-2089-6. Separation of carling from Turret 6 in way of connection to main deck at frame 122, centerline.

SECRET

USS ARKANNAS (BB33) Page 128 of 177 Pages




AA-CR-92-1775-8. Shadow on main deck frame 129, port, main deck.

Page 129 of 177 Pages

USS ARKANSAS (BB33)

9526



AA-CR-80-1895-12. General view of displaced equipment on main deck. Looking aft and to starboard from mainmast.

SECRET

Page 130 of 177 Pages


USS ARKANSAS (BB33)



AA-CR-92-1775-2. Looking forward from frame 85, main deck. port. General view showing displaced equipment.

Page 131 of 177 Pages


USS ARKANSAS (BB33)



AA-CR-92-1775-5. Looking aft at displaced and damaged equipment. Frame 85, starboard, main deck.

SECRET

USS ARKANSAS (BB33) Page 132 of 177 Pages



AA-CR-92-1775-11. General view looking aft from bridge deck.

Page 133 of 177 Pages

USS ARKANSAS (BB33)

. 92



AA.-CR.-68-2090-8. Condition of starboard blister, top and shell plating aft.

SECRET

Page 134 of 177 Pages


USS ARKANSAS (BB33)



AA-CR-68-2096-8. Looking aft from frame 129, starboard, at disned shell plating and framing.

Page 135 of 177 Pages

USS ARKANSAS (BB33)



AA-CR-68-2091-11. Looking outboard at failure of weld between shell and main deck, frame 64 to 6., starboard, second deck.

SECRET


Page 136 of 177 Pages



AA-CR-68-2030-7. Dished plating on starboard blister aft of frame 50.

Page 137 of 177 Pages

USS ARKANCAS (FILDS)



AA-CR-68-2090-9. Deflection of starboard blister plating above water-line, vicinity of frame 100.

SECRET

Page 138 of 177 Pages



AA-CR-68-2091-12. Looking forward in crew's space, frames 62 to 69, starboard, showing deflection of overhead.

Page 139 of 177 Pages

USS ARKANSAS (BB33)

9256



AA>CR-58-2096-12. Second deck, sick bay, frame 104, starboard, showing distorted frame brackets.

SECRET

Page 140 of 177 Pages

USS ARKANSAS (BB33)

9526



AA-CR-68-2096-2. Crew's space, second deck, looking aft from frame 117, starboard, at supporting structure under deflected main deck.

Page 141 of 177 Pages

USS ARKANSAS (BB33)

AA-CR-68-2086-11. Crew's space, second deck aft. Looking aft and inboard from frame 120, port, at damage in space under sagged area of main deck.

SECRET

Page 142 of 177 Pages



AA-CR-68-2096-3. Crew's quarters, second deck, aft. Looking forward from frame 127, port, at damage to supporting structure below deflected main deck. Vent controller enclosure and support damaged, mechanism operable. SECRET

Page 143 of 177 Pages

USS ARKANSAS (RB33)




AA-CR-68-2056-5. Looking to port at damage to equipment and supporting structure below deflected main deck, frame 125, centerline.

SECRET

Page 144 of 177 Pages

USS ARKANSAS (BB33)

9254



AA-CR-68-2096-10. Distortion of frame brackets, second deck, frame 122 and 123, port. Cables in rack pulled out due to structural distortion.

Fage 145 of 177 Pages

USS ARKANSAS (BB33)

Page 146 of 177 Pages

SECRET

AA-CR-175-2134-6. Second deck, looking aft and to starboard at the port builthead of crew's washroom, frames 125 1/2 and 129.



AA-CR-175-2134-4. Close-up of second deck failure in way of forward bulkhead of crew's washroom, frame 125 1/2.

Page 147 of 177 Pages

USS ARKANSAS (BB33)

9256



AA-CR-68-2096-4. Looking to port at deflection of second deck, frame 125 1/2, in way of bulkhead under deflected main deck.

SECRET

Page 148 of 177 Pages



AA-CR-68-2096-6. Failure of connection and damage to second deck in way of ventilation duct to D-111 at frame 125, starboard.

Sage 149 of 177 Pages

USS ARKANSAS (BB33)

9255




AA-CR-68-2096-9. Third deck, looking to starbcard at bent stanchion under second deck, frame 125, centerline. Note water on deck.

SECRET

Page 150 of 177-Pages

USS ARKANSAS (BB33)

電視の表にも期を通り、1998を含めているです。 後いないのうがいない こんじゅう



AA-CR-68-2096-7. Failure of ventilation duct to D-111 at frame 125, starboard, under main deck.

Page 151 of 177 Pages


USS ARKANSAS (BB33)

9526

Page 152 of 177 Pages

SECRET


AA-CR-68-2097-10. Looking forward at scorched paint on vent intake, main deck, frame 80, starboard.



AA-CR-68-2097-9. Second deck, frames 82, starboard, damage to vent duct.

Page 153 of 177 Pages


USS ARKANSAS (BB33)



AA-CR-68-2097-8. Third deck, frame 82, starboard, damage to vent duct.

SECRET

USS ARKANSAS (BB33) Page 154 of 177 Pages



AA-CR-68-2147-1. Failure of longitudinal bulkby ...gine room, looking to starboard between frames 98-99. Note buckle in bulkhead at left of beam connection.

Page 155 of 177 Pages

USS ARKANSAS (BB33)

AA-CR-68-2146-12. Failure of longitudinal bulkhead engine room, looking to port between frames 99-100, note buckle in bulkhead at left of beam connection.

SECRET

Page 156 c. 177 Pages




AA-CR-62-1876-5. No. 3 boiler, starboard side casing, upper section.

USS ARKANSAS (BB33) Page 157 of 177 Pages

AA-CR-62-1876-6. No. 3 boiler, starboard side casing, upper section.

SECRET

USS ARKANSAS (BB33)
Page 158 of 177 Pages



AA-CR-62-1876-7. No. 3 boiler, port side casing, upper section.

Page 159 of 177 Pages

USS ARKANSAS (BB33)



AA-CR-62-1876-8. No. 3 boiler, port side casing, near water drum.

SECRET

USS ARKANSAS (BB33)
Page 160 of 177 Pages 9254



AA-CR-62-1876-3. No. 3 botler, starboard side casing, near mud drum,

USS ARKANSAS (BB33) Page 161 of 177 Pages

SECRET



AA-CR-62-1876-4. No. 3 boiler, starboard side casing, near mud drum,

SECRET

USS ARKANSAS (BB33) Page 162 of 177 Pages



AA-CR-62-1876-9. Lower stack, from starboard,

Page 163 of 177 Pages

USS ARKANSAS (BB33)



AA-CR-62-1876-10. Jpper stack, from starboard.

SECRET

USS ARKANGAS (BB33) Page 164 of 177 Pages



AA-CR-80-1897-1. Stack connection, upper deck.

USS ARKANGAS (BR33) Page 165 of 177 Pages

AA-CR-80-185. Stack connection, upper deck.


SECRET

USS ARKANKAS (BB33) Page 166 of 177 Pages



AA-CR-80-1897-3. Stack connection, showing division plates.


USS ARKANSAS (BB33) Page 167 of 177 Pages



AA-CR-62-1882-12. Temporary stack.

SECRET

USS ARKANSAS (BB33) Page 168 of 177 Pages



AA-CR-68-2091-8. Tempofary stack erected after Test A.

USS ARKANGAS (BB33)
Page 169 of 177 Pages


SECRET

Page 170 of 177 Pages

AA-CR-68-2025-8. Temporary stack erected after Test A.

USS ARKANSAS (BB33)


952.5



AA-CR-62-2168-3. After warping winch.

Page 171 of 177 Pages

USS ARKANSAS (BB33)



AA-CR-62-1882-10, Starbcard crane.

SECRET

USS ARKANSAS (BB33)
Page 172 of 177 Pages




AA-CR-62-1882-11. Starboard crane.

USS ARKANSAS (BB33) Page 173 of 177 Pages

AA-CR-68-209f-1. Starboard crane.

USS ARKANSAS (BB33)
Page 174 of 177 Pages




AA-CR-175-2156-4. Deck Winch Controller-Deflection of the main deck over head bent the operating rod extending through the deck, distorted the controller supports and broke several contact fingers.

USS ARKANNAS (BB33)

Page 175 of 177 Pages

AA-CR-175-2135-5. Photo shows cable with beads of insulation protruding through armor. Cable is on after side of foremast.

USS ARKAIGAS (BB3S)



AA-CR-80-1895-4. 36" searchlight blown from platform on mainmas

CONFIDENTIAL MONIC MENTAL

Page 177 of 177 Pages CONFIDENTIAL

Charles of the color of the col

CAUTION

This Document Contains
ATOMIC WEAPONS INFORMATION

NOTICE

This document contains atomic weapons information. Distribution is limited to recipients authorized by the Defense Atomic Support Agency (DOD) and/or the Division of Military Application (AEC)



Defense Special Weapons Agency 6801 Telegraph Road Alexandria, Virginia 22310-3398

10 April 1997

MEMORANDUM FOR DEFENSE TECHNICAL INFORMATION CENTER ATTENTION: OMI/Mr. William Bush

SUBJECT: Declassification of Reports

The Defense Special Weapons Agency (formerly Defense Nuclear Agency) Security Office has reviewed and declassified the following reports:

	AD-366718	XRD-32-Volume 3
	AD-366726~	XRD-12-Volume 2
	AD-366703~	XRD-16-Volume 1
	AD-366702-	XRD-14-Volume 2
	AD-376819L~	XRD-17-Volume 2
	AD-366704~	XRD-18
	AD-367451	XRD-19-Volume 1
	AD-3667007 5 -	XRD-20-Volume 2 AD-366705
	AD-376028L-	XRD-4
	AD-366694 -	XRD-1
	AD-473912 -	XRD-193
	AD-473891-	XRD-171
	AD-473899	XRD-163
	AD-473887~	XRD-166 ST-A 28-AN80
_	AD-473888 -	XRD-166 XRD-167 ST-A 28 JAN80 MADE TAIGET
	AD-473889 -	XRD-168

TRC

SUBJECT: Declassification of Reports

AD-B197749	XRD-174
AD-473905~	XRD-182
AD-366719	XRD-33 Volume 4
AD-366700	XRD-10
AD-366712-	XRD-25 Volume 1
AD-376827L	XRD-75
AD-366756 *	XRD-73
AD-366757-	XRD-74
AD-366755 *	XRD-72
AD-366754	XRD-71
AD-366710~	XRD-23 Volume 1
AD-366711-	XRD-24 Volume 2
AD-366753	XRD-70
AD-366749~	XRD-66
AD-366701~	XRD-11
AD-366745	XRD-62.

All of the cited reports are now approved for public release; distribution statement "A" applies.

Andith Jarrett arrett

Chief, Technical Resource Center

copy furn: FC/DSWA (DASIAC)

KSC

Completed L.w